

## River Thames – emergency river restriction

**50 metres upstream of Windsor and Eton Footbridge  
Windsor Reach**

**Wednesday 17 October 2018 until further notice**

**Fallen tree 50 metres upstream of Windsor and Eton  
Footbridge**

**Directions for navigation and general information during this incident:**

A tree has fallen 50 metres upstream of Windsor and Eton Footbridge. It is extending half way across the river. Our team is working as quickly as possible to arrange the removal of the tree. In the meantime, passage is still possible through the centre arch of Windsor and Eton Footbridge with extreme care and caution. Do not attempt to navigate through the Windsor, left arch of the footbridge.

We apologise for any inconvenience this causes and thank you for your patience during this time.

**Note:** All directions as to left and right are given looking upstream.

**Barry Russell MBE  
Harbourmaster  
17 October 2018**